



## Tool List

### Salem Welding classes with Terry Calderwood

#### All Classes

Leather gloves  
Leather shoes  
Hood with # 10 lenses (ARC, M.I.G, T. I.G)  
Safety glasses  
Extra plastic cover lenses  
Ear Plugs (recommended, but not required)

#### ARC

Chipping Hammer  
Wire brush  
(2) 11R or 11sp vise grips  
Fillet weld gauges (advanced)

#### M.I.G

Tweco .035 and .045 contact tips (#14, 14H, or 14T only)  
Wire cutters  
(2) 11r or 11sp vise grips

#### Oxy/Acetylene

Tip Cleaner  
Pliers  
Striker  
Goggles/glasses/ face shield in #4 or 5 shade

#### T.I.G.

3/32 2% thoriated tungsten  
3/32 pure tungsten  
3/32 collets  
3/32 collet bodies  
Back cap  
Gas cups  
Pliers  
SS toothbrush

Any questions you can call 503.3998690,  
or e-mail the Instructor [tcalderv@cp.chemeketa.edu](mailto:tcalderv@cp.chemeketa.edu)